


General Information

Date & Time: 05, Nov, 2024 14:57

Make	Toyota	Model	Vios
YOM	2024	Mileage	4,169
Registration No.	NKC6964	Chassis No.	PA1B18F3XR4247705
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.6	127	121	123
2	Boot Lid	117.6	117	115	121
3	Roof	112.0	118	107	108/115
4	Left Front Fender	106.3	105	104	110
5	Left Front Door	114.6	116	117	111
6	Center Panel Left				
7	Left Rear Door	155.0	150	149	166
8	Left Back Panel	212.3	193	250	194
9	Right Front Fender	115.6	119	110	118
10	Right Front Door	118.3	112	119	124
11	Center Panel Right				
12	Right Rear Door	113.3	108	112	120
13	Right Back Panel	118.3	119	116	120

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
hairlines scratch & swirl marks door ding protection