


General Information

Date & Time: 25, Jun, 2025 08:14

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	1,838
Registration No.	DBQ2536	Chassis No.	MHKB3FE10RK003701
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	58.5	52	67	56
2	Boot Lid	52.8	50	63	46
3	Roof	52.2	62	52	50/45
4	Left Front Fender	57.1	57	50	65
5	Left Front Door	48.2	52	45	47
6	Center Panel Left				
7	Left Rear Door	128.6	54	284	48
8	Left Back Panel	59.3	65	55	57
9	Right Front Fender	61.4	63	53	68
10	Right Front Door	50.1	59	46	45
11	Center Panel Right				
12	Right Rear Door	58.9	62	58	58
13	Right Back Panel	59.3	61	55	63

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Rear Door - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Front Panel - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet, with jack and tools, with spare tire, no LTO plate