


General Information

Date & Time: 05, Nov, 2024 19:15

Make	Toyota	Model	Vios
YOM	2024	Mileage	3,938
Registration No.	DBO4223	Chassis No.	PA1B18F38R4239439
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	230.0	231	226	233
2	Boot Lid	118.3	113	118	124
3	Roof	119.5	119	127	112/120
4	Left Front Fender	112.0	112	113	111
5	Left Front Door	109.3	110	107	111
6	Center Panel Left				
7	Left Rear Door	116.6	118	115	117
8	Left Back Panel	127.6	134	128	121
9	Right Front Fender	117.6	115	119	119
10	Right Front Door	113.3	113	112	115
11	Center Panel Right				
12	Right Rear Door	118.3	115	117	123
13	Right Back Panel	123.6	125	123	123

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes	Remarks Bonnet - Repair Traces - Yes / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / Roof - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

light scratches around the exterior.