

General Information

Date & Time: 23, Jun, 2025 09:55

Make	Mitsubishi	Model	Mirage
YOM	2024	Odo Meter Reading	11,793
Registration No.	NIT5453	Chassis No.	PAEA13TJRPA020746
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	115	111	115
2	Boot Lid	103.0	100	107	102
3	Roof	97.3	92	100	100/98
4	Left Front Fender	103.6	105	104	102
5	Left Front Door	98.3	99	97	100
6	Center Panel Left				
7	Left Rear Door	264.6	489	149	156
8	Left Back Panel	183.0	200	180	169
9	Right Front Fender	100.4	98	103	100
10	Right Front Door	171.6	174	161	180
11	Center Panel Right				
12	Right Rear Door	150.3	143	149	159
13	Right Back Panel	97.3	100	96	96

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Minimal / Mat Other - Grime - Small / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Seat - Grime - Small / Sunvisor, Sunglass Holder - Crinkle - Small</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With warranty booklet, spare tire and jack. Without tools and seat cover. 1 key. No LTO plate</p>