

General Information

Date & Time: 05, Nov, 2024 13:23

Make	Toyota	Model	Vios
YOM	2024	Mileage	14,166
Registration No.	DBO4289	Chassis No.	PA1B18F30P4238623
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.0	126	116	124
2	Boot Lid	120.6	117	122	123
3	Roof	114.7	118	107	111/123
4	Left Front Fender	116.3	119	116	114
5	Left Front Door	113.3	115	110	115
6	Center Panel Left				
7	Left Rear Door	117.3	115	122	115
8	Left Back Panel	123.0	131	126	112
9	Right Front Fender	118.3	121	120	114
10	Right Front Door	115.0	112	117	116
11	Center Panel Right				
12	Right Rear Door	120.0	112	116	132
13	Right Back Panel	122.3	120	117	130

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Medium / (R) Front Floor Lag - Grime - Small / Rear Seat - Grime - Medium	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Rust, Corrosion - Minimal / (R) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
swirlmarks and hairline scratches around the exterior.