

General Information

Date & Time: 24, Jun, 2025 17:09

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	23,053
Registration No.	GAP5845	Chassis No.	PA1B18F34N4199970
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	114	100	114
2	Boot Lid	101.6	105	100	100
3	Roof	100.9	107	99	99/99
4	Left Front Fender	96.1	93	94	101
5	Left Front Door	98.2	96	102	96
6	Center Panel Left				
7	Left Rear Door	98.5	107	98	91
8	Left Back Panel	111.0	112	111	110
9	Right Front Fender	98.7	98	97	102
10	Right Front Door	101.1	99	102	103
11	Center Panel Right				
12	Right Rear Door	102.3	100	103	104
13	Right Back Panel	105.0	107	98	110

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A		Exterior Evaluation : D	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small		Remarks Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Front Fender, Molding - Crack, Gap - Medium / Bonnet, Headlight - Crack, Gap - Medium / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / Roof - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist	

Inspector Notes

with LTO plate and sparetire. no warranty booklet, Jack And Tools. scratch headlight and tail light.