


General Information

Date & Time: 30, Jun, 2025 11:56

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	31,006
Registration No.	NHS2015	Chassis No.	PA1B18F37R4251887
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	127.3	129	122	131
2	Boot Lid	118.6	117	117	122
3	Roof	120.2	125	125	118/113
4	Left Front Fender	106.3	112	103	104
5	Left Front Door	113.3	117	113	110
6	Center Panel Left				
7	Left Rear Door	110.9	120	115	98
8	Left Back Panel	125.3	138	126	112
9	Right Front Fender	149.0	226	105	116
10	Right Front Door	116.6	114	119	117
11	Center Panel Right				
12	Right Rear Door	118.0	114	117	123
13	Right Back Panel	119.3	108	125	125

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Minimal	Remarks (R) Front Fender - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, with jack, incomplete tools, with spare tire, with LTO plate