

General Information

Date & Time: 30, Jun, 2025 13:03

Make	Toyota	Model	Hilux
YOM	2024	Odo Meter Reading	16,371
Registration No.	NIU5840	Chassis No.	MR0AB8DD9R5037401
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	181.6	185	174	186
2	Boot Lid	95.8	96	100	91
3	Roof	111.2	103	106	122/114
4	Left Front Fender	116.3	119	113	117
5	Left Front Door	108.3	114	104	107
6	Center Panel Left	132.3	131	138	128
7	Left Rear Door	111.3	119	110	105
8	Left Back Panel	113.0	112	112	115
9	Right Front Fender	114.0	107	108	127
10	Right Front Door	104.3	106	106	101
11	Center Panel Right	129.6	134	135	120
12	Right Rear Door	106.0	101	101	116
13	Right Back Panel	102.4	111	98	98

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	B
The diagram shows the interior of a vehicle from a top-down perspective. Numbered areas include: 1 (front dashboard), 2 (rear headrest area), 3 (center console), 4 (passenger seat), 5 (driver's seat), 6 (right side door panel), 7 (rear bench seat), 8 (rear floor mat), 9 (left front seat), and 10 (left side door panel). Defect codes are placed as follows: A1 at the passenger seat headrest, X at the passenger seat base, D1 on the center console, and Y2 on the rear bench seat.		The diagram shows the exterior of a vehicle from a top-down perspective. Numbered areas include: 1 (front left fender), 2 (front left wheel), 3 (front left mirror), 4 (hood), 5 (front right wheel), 6 (front right fender), 7 (front grille/bumper), 8 (hood), 9 (front right mirror), 10 (front right fender), 11 (front right wheel), 12 (front right door), 13 (roof), 14 (rear window), 15 (rear door), 16 (rear bumper), 17 (rear trunk), 18 (rear left wheel), 19 (rear left fender). Defect codes are placed as follows: A1 at various points on the front fenders, mirrors, hood, rear door, rear fender, and rear wheel; AU2 at the front left wheel; and A3 at the roof.	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Rear Seat - Grime - Small / Glove Box - Worn, Scratch, Cut, Crack - Minimal / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Console, Switches, Vents - Worked - Minimal		Remarks Bonnet - Repair Traces - Yes / Bonnet, Headlight - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Minimal / Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Side Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal	
Frame Evaluation :	A	Functional Evaluation :	A
Remarks Defects not found		Remarks Defects not found	

Inspector Notes

with LTO plate ,with warranty booklet, with jack, no tools, with spare tire
