


General Information

Date & Time: 01, Jul, 2025 09:57

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	26,417
Registration No.	NKB5742	Chassis No.	PA1B18F39R4249364
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	146.3	160	126	153
2	Boot Lid	132.3	132	120	145
3	Roof	131.5	139	125	128/134
4	Left Front Fender	120.0	125	113	122
5	Left Front Door	124.6	122	121	131
6	Center Panel Left				
7	Left Rear Door	125.6	128	123	126
8	Left Back Panel	141.6	149	149	127
9	Right Front Fender	122.0	124	118	124
10	Right Front Door	130.3	146	121	124
11	Center Panel Right				
12	Right Rear Door	127.0	128	125	128
13	Right Back Panel	131.3	136	125	133

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Minimal / Ceiling - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Roof - Dent - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, with warranty booklet, with jack and tools, with spare tire