


General Information

Date & Time: 27, Jun, 2025 15:36

Make	Toyota	Model	Yaris Cross
YOM	2024	Odo Meter Reading	12,275
Registration No.	NOV1986	Chassis No.	MHFAB8BF9P0013438
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	147.0	163	148	130
2	Boot Lid	146.0	144	148	146
3	Roof	137.2	152	160	121/116
4	Left Front Fender	147.6	144	142	157
5	Left Front Door	155.3	150	152	164
6	Center Panel Left				
7	Left Rear Door	162.3	157	141	189
8	Left Back Panel	168.3	175	153	177
9	Right Front Fender	152.3	151	160	146
10	Right Front Door	154.3	164	154	145
11	Center Panel Right				
12	Right Rear Door	148.6	157	137	152
13	Right Back Panel	159.3	168	148	162

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Minimal	Remarks (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Minimal / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, with warranty booklet, with jack and tools, with spare tire