

General Information

Date & Time: 27, Jun, 2025 15:18

Make	Toyota	Model	Hiace
YOM	2020	Odo Meter Reading	161,243
Registration No.	CAV6326	Chassis No.	JTFNAFAP8L8015912
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	73.2	77	70	73
2	Boot Lid	214.3	289	186	168
3	Roof	82.2	74	67	81/107
4	Left Front Fender	66.6	66	70	64
5	Left Front Door	71.2	81	72	61
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	65.6	64	65	68
9	Right Front Fender	70.6	74	74	65
10	Right Front Door	63.8	62	61	68
11	Center Panel Right	91.7	90	105	80
12	Right Rear Door	135.6	127	144	136
13	Right Back Panel	177.3	158	187	187

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / Overall Interior - Worn as per age - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Center Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Center Panel - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Dent - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Modified - Large / Front Bumper, Grille, Lamps - Scratch - Medium / Rear Bumper, Lamps, Panels - Modified - Large / Bonnet, Headlight - Dent - Small / Roof - Dent - Medium / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet, with jack, no tools, with spare tire, with LTO plate, scratches on headlight and taillight, yellowish headlight, power window button on driver side issue, many touch up panel