


General Information

Date & Time: 30, Jun, 2025 13:33

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	18,760
Registration No.	NIP9288	Chassis No.	PA1B18F36P4223933
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.3	130	111	126
2	Boot Lid	122.3	122	123	122
3	Roof	123.2	127	106	112/148
4	Left Front Fender	108.6	108	107	111
5	Left Front Door	110.6	113	110	109
6	Center Panel Left				
7	Left Rear Door	119.0	118	120	119
8	Left Back Panel	132.3	156	125	116
9	Right Front Fender	131.3	114	115	165
10	Right Front Door	109.6	111	107	111
11	Center Panel Right				
12	Right Rear Door	113.3	105	112	123
13	Right Back Panel	109.3	112	104	112

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
The diagram shows the interior of a vehicle from a top-down perspective. Numbered areas include: 1 (front passenger headrest), 2 (rear seat backrest), 3 (center console), 4 (driver's side floor area), 5 (passenger's side floor area), 6 (rear door sill), 7 (center rear bench), 8 (front footwell), 9 (driver's seat), and 10 (passenger's seat). Defect codes are placed near specific areas: Y1 (near 10), C A2 (near 5), and 6 (near 6).	The diagram shows the exterior of a vehicle from three perspectives: front, side, and rear. Numbered areas include: 1 (front left wheel), 2 (front right wheel), 3 (hood), 4 (front bumper), 5 (front grille), 6 (front fender), 7 (side mirror), 8 (side door), 9 (rear door), 10 (rear quarter panel), 11 (rear window), 12 (rear bumper), 13 (rear fender), 14 (rear wheel), and 15 (rear trunk). Defect codes are placed near specific areas: A1 (near 1, 9), A2 (near 2, 6, 7, 10, 12), AU1 (near 11), AU2 (near 12), AU3 (near 13), AU4 (near 14), B (near 15), SC (near 15), U (near 15), X (near 15), and Y (near 15).
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Medium / (L) Front Floor Mat - Worked - Small / Carpet - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Minimal	Remarks (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet, no jack, no tools, with spare tire, with LTO plate