

General Information

Date & Time: 25, Jun, 2025 18:54

Make	Mazda	Model	CX-9
YOM	2023	Odo Meter Reading	70,773
Registration No.	NFA8013	Chassis No.	JM7TC4WLAR0477522
CC	2.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	163.6	169	161	161
2	Boot Lid	79.6	81	82	77
3	Roof	72.8	68	69	86/68
4	Left Front Fender	77.4	77	77	79
5	Left Front Door	84.9	86	86	84
6	Center Panel Left				
7	Left Rear Door	84.2	86	83	84
8	Left Back Panel	86.2	87	86	87
9	Right Front Fender	70.6	72	66	74
10	Right Front Door	83.3	84	79	87
11	Center Panel Right				
12	Right Rear Door	86.0	83	81	94
13	Right Back Panel	87.0	88	88	85

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal	Remarks Bonnet - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate and Jack, Spare tire and incomplete tools. no warranty booklet and scratch headlight and tail light.