

General Information

Date & Time: 28, Jun, 2025 08:01

Make	Toyota	Model	Innova
YOM	2024	Odo Meter Reading	33,327
Registration No.	NHA4694	Chassis No.	PA2JA8EM4P0133673
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.0	103	112	100
2	Boot Lid	93.7	94	89	98
3	Roof	89.1	88	86	91/91
4	Left Front Fender	94.4	91	96	96
5	Left Front Door	96.4	94	95	100
6	Center Panel Left				
7	Left Rear Door	99.5	100	103	96
8	Left Back Panel	99.1	99	100	99
9	Right Front Fender	100.3	101	103	97
10	Right Front Door	99.1	95	103	99
11	Center Panel Right				
12	Right Rear Door	97.6	94	99	100
13	Right Back Panel	104.6	106	103	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Grime - Medium / Mat Other - Grime - Minimal / (R) Rear Trim - Grime - Minimal / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Small / Sunvisor, Sunglass Holder - Loose, Deformed - Medium	Remarks (R) Mirror - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
All interior lights missing. interior light assembly front and 2nd row loose. Without warranty booklet, tools and jack. With spare tire and seat cover. 2 keys. With LTO plate.