


General Information

Date & Time: 30, Jun, 2025 15:50

Make	Toyota	Model	Wigo
YOM	2022	Odo Meter Reading	10,499
Registration No.	NFH6638	Chassis No.	MHKA4DF5FNJ066368
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.4	97	104	106
2	Boot Lid	118.0	103	132	119
3	Roof	97.4	93	100	98/98
4	Left Front Fender	120.6	112	118	132
5	Left Front Door	124.3	131	125	117
6	Center Panel Left				
7	Left Rear Door	131.0	134	124	135
8	Left Back Panel	117.3	124	109	119
9	Right Front Fender	108.4	112	114	99
10	Right Front Door	119.6	111	124	124
11	Center Panel Right				
12	Right Rear Door	120.0	127	123	110
13	Right Back Panel	117.6	122	110	121

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / Roof - Dent - Minimal / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with LTO plate, with warranty booklet, with jack and tools, with spare tire, headlight scratch