

General Information

Date & Time: 28, Jun, 2025 10:25

Make	Suzuki	Model	Dzire
YOM	2020	Odo Meter Reading	41,515
Registration No.	NFV5063	Chassis No.	MA3ZF63S2LA599713
CC	1.2	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.8	95	102	93
2	Boot Lid	85.7	85	88	84
3	Roof	97.8	79	97	108/108
4	Left Front Fender	97.7	109	98	86
5	Left Front Door	100.5	111	98	93
6	Center Panel Left				
7	Left Rear Door	108.1	95	97	132
8	Left Back Panel	108.5	125	104	97
9	Right Front Fender	209.0	172	295	160
10	Right Front Door	100.8	99	99	104
11	Center Panel Right				
12	Right Rear Door	90.3	91	89	91
13	Right Back Panel	91.0	92	90	91

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Steering Wheel - Worn, Peel, Crack - Small / Sunvisor, Sunglass Holder - Grime - Small	Remarks (R) Front Fender - Repair Traces - Yes / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With warranty booklet, spare tire, and leather seat cover. Without jack and tools. 1 key. With LTO plate