

General Information

Date & Time: 28, Jun, 2025 14:34

Make	Suzuki	Model	APV
YOM	2020	Odo Meter Reading	27,558
Registration No.	NED4453	Chassis No.	MHYDN71V4LJ402071
CC	1.6	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.6	99	102	88
2	Boot Lid	145.6	142	147	148
3	Roof	88.2	80	78	98/98
4	Left Front Fender	182.3	255	134	158
5	Left Front Door	139.6	130	131	158
6	Center Panel Left				
7	Left Rear Door	130.6	154	127	111
8	Left Back Panel	158.3	166	157	152
9	Right Front Fender	139.6	145	131	143
10	Right Front Door	142.0	152	129	145
11	Center Panel Right				
12	Right Rear Door	184.3	252	142	159
13	Right Back Panel	137.6	140	130	143

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain Remarks (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / Sunvisor, Sunglass Holder - Crinkle - Small	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap Remarks (L) Front Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Faded(Color, Gloss) - Yes / Front Bumper, Grille, Lamps - Scratch - Large / (R) Mirror - Faded(Color, Gloss) - Yes / Roof - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

taillight not working. Without warranty booklet and tools. With spare tire and jack. 1 key. With LTO plate. aftermarket headliner.