

General Information

Date & Time: 05, Nov, 2024 13:33

Make	Toyota	Model	Vios
YOM	2024	Mileage	13,639
Registration No.	EAG9617	Chassis No.	PA1B18F37R4246219
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	140.3	152	129	140
2	Boot Lid	133.3	122	142	136
3	Roof	128.2	138	128	120/127
4	Left Front Fender	116.0	119	110	119
5	Left Front Door	121.6	122	120	123
6	Center Panel Left				
7	Left Rear Door	129.0	132	126	129
8	Left Back Panel	137.3	154	131	127
9	Right Front Fender	128.0	125	129	130
10	Right Front Door	135.3	137	139	130
11	Center Panel Right				
12	Right Rear Door	132.0	125	132	139
13	Right Back Panel	135.0	134	123	148

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray b : Loose, Deformed c : Animal Hair d : Smell e : Cigarette Burns f : Defective g : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes	Remarks (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (L) Step, In-panel, Side Spoiler - Dent - Large / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / Roof - Dent - Minimal / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
hairline scratches and swirl marks/ no floor matt