

General Information

Date & Time: 28, Jun, 2025 18:08

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	19,818
Registration No.	NKF7463	Chassis No.	PA1B18FF32R4268029
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	106	112	109
2	Boot Lid	112.0	111	109	116
3	Roof	101.2	103	101	100/101
4	Left Front Fender	101.4	102	103	99
5	Left Front Door	103.8	101	100	111
6	Center Panel Left				
7	Left Rear Door	108.6	118	104	104
8	Left Back Panel	112.0	122	104	110
9	Right Front Fender	103.6	104	108	99
10	Right Front Door	100.1	102	99	99
11	Center Panel Right				
12	Right Rear Door	106.0	103	99	116
13	Right Back Panel	105.0	111	102	102

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Mat Other - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Small	Remarks (L) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Roof - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
Crack taillight, Without warranty booklet and seat cover. Incomplete tools. With spare tire and jack. 3 keys. With LTO plate.