

General Information

Date & Time: 30, Jun, 2025 13:31

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	17,446
Registration No.	DBP9211	Chassis No.	PA1B18F38R42693
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.3	121	113	112
2	Boot Lid	121.0	117	120	126
3	Roof	102.1	109	101	102/97
4	Left Front Fender	106.6	107	107	106
5	Left Front Door	105.6	104	101	112
6	Center Panel Left				
7	Left Rear Door	102.0	112	100	94
8	Left Back Panel	111.3	121	103	110
9	Right Front Fender	113.0	112	117	110
10	Right Front Door	109.6	106	116	107
11	Center Panel Right				
12	Right Rear Door	101.1	99	101	103
13	Right Back Panel	112.3	102	114	121

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Small	Remarks (L) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With warranty booklet, spare tire, seat cover and jack. Without tools. 3 keys. With LTO plate.