

General Information

Date & Time: 05, Nov, 2024 10:33

Make	Toyota	Model	Vios
YOM	2022	Mileage	19,882
Registration No.	DAS3406	Chassis No.	PA1B18F35N4191246
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.6	117	122	126
2	Boot Lid	128.6	121	131	134
3	Roof	110.5	115	109	108/110
4	Left Front Fender	107.0	111	104	106
5	Left Front Door	116.6	117	118	115
6	Center Panel Left				
7	Left Rear Door	116.0	113	115	120
8	Left Back Panel	117.6	121	115	117
9	Right Front Fender	113.3	116	107	117
10	Right Front Door	113.6	112	115	114
11	Center Panel Right				
12	Right Rear Door	113.6	105	114	122
13	Right Back Panel	118.6	119	119	118

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / Dashboard - Traces of Adhesive Tape - Yes / Trunk Room - Loose, Deformed, Grime - Small / (R) Front Seat - Worn - Yes	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
front right seat& rear seat dirt marks