


General Information

Date & Time: 01, Jul, 2025 16:39

Make	Mercedes-Benz	Model	E 200
YOM	2017	Odo Meter Reading	11,801
Registration No.	NCN7988	Chassis No.	WDD2130421A125329
CC	2.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	145.0	142	138	155
2	Boot Lid	129.3	128	131	129
3	Roof	147.0	161	139	135/153
4	Left Front Fender	153.6	154	150	157
5	Left Front Door	161.6	147	175	163
6	Center Panel Left				
7	Left Rear Door	151.6	154	155	146
8	Left Back Panel	132.6	134	132	132
9	Right Front Fender	144.6	141	147	146
10	Right Front Door	168.0	166	166	172
11	Center Panel Right				
12	Right Rear Door	157.0	154	160	157
13	Right Back Panel	137.3	141	136	135

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Tyre - Crack, Cut - Yes / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate. no Tools and jack, Sparetire and warranty booklet.