

General Information

Date & Time: 05, Nov, 2024 18:40

Make	Suzuki	Model	XL7
YOM	2023	Mileage	7,270
Registration No.	NIS8263	Chassis No.	MHYNC22S6RJ100789
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	127.3	142	115	125
2	Boot Lid	105.6	104	108	105
3	Roof	112.5	110	105	120/115
4	Left Front Fender	110.0	110	111	109
5	Left Front Door	107.0	119	96	106
6	Center Panel Left				
7	Left Rear Door	105.0	104	103	108
8	Left Back Panel	109.3	114	109	105
9	Right Front Fender	110.0	106	108	116
10	Right Front Door	102.5	108	96	104
11	Center Panel Right				
12	Right Rear Door	105.6	105	104	108
13	Right Back Panel	103.0	105	100	104

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Defects not found
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
no issues/ fresh unit/