

General Information

Date & Time: 05, Nov, 2024 17:42

Make	Toyota	Model	Vios
YOM	2022	Mileage	18,346
Registration No.	NFE6832	Chassis No.	PA1B18F35N4187701
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.0	119	119	125
2	Boot Lid	113.6	117	110	114
3	Roof	108.3	119	99	108/108
4	Left Front Fender	116.3	113	118	118
5	Left Front Door	110.3	108	113	110
6	Center Panel Left				
7	Left Rear Door	113.6	112	118	111
8	Left Back Panel	120.0	122	120	118
9	Right Front Fender	108.6	109	107	110
10	Right Front Door	107.0	110	103	108
11	Center Panel Right				
12	Right Rear Door	106.6	101	102	117
13	Right Back Panel	114.0	111	112	119

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / (L) Front Floor Lag - Grime - Small / Rear Seat - Grime - Minimal / Ceiling - Grime - Small / (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Medium	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / Roof - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
light scratches around the exterior. adhesive marks at the windshield. aftermarket rear passenger mirrors. front passenger tint crack