


General Information

Date & Time: 16, Jul, 2025 11:02

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	7,845
Registration No.	NHU3699	Chassis No.	PA1B18F32R4270458
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.1	99	97	98
2	Boot Lid	108.3	105	110	110
3	Roof	100.4	107	108	92/95
4	Left Front Fender	89.2	94	88	86
5	Left Front Door	98.5	97	97	102
6	Center Panel Left				
7	Left Rear Door	104.0	111	101	100
8	Left Back Panel	116.3	109	108	132
9	Right Front Fender	94.7	90	96	98
10	Right Front Door	97.6	96	95	102
11	Center Panel Right				
12	Right Rear Door	97.5	93	95	105
13	Right Back Panel	102.8	102	98	108

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Wiper - Function - Weak

Inspector Notes

with warranty booklet and LTO Plate, Jack and Sparetire. no Tools and Scratch headlight and tail light. wiper not working.