

General Information

Date & Time: 07, Jul, 2025 17:23

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	35,219
Registration No.	DAQ1946	Chassis No.	PA1B18F35N4172535
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	176.0	178	159	191
2	Boot Lid	117.0	112	116	123
3	Roof	116.7	115	111	118/123
4	Left Front Fender	93.6	98	95	88
5	Left Front Door	148.6	141	144	161
6	Center Panel Left				
7	Left Rear Door	116.6	129	115	106
8	Left Back Panel	134.0	141	138	123
9	Right Front Fender	109.6	111	107	111
10	Right Front Door	112.3	119	110	108
11	Center Panel Right				
12	Right Rear Door	114.0	106	111	125
13	Right Back Panel	120.3	118	115	128

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Large	Remarks Bonnet - Repair Traces - Yes / Member (Bolted) - Dent - Yes / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Repair mark - Yes / (L) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Repair mark - Yes / Bonnet, Headlight - Scratch & Dent - Small / Roof - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet and LTO plate, Jack and sparetire, Incomplete tools. scratch headlight and tail light. missing front emblem. unusual sound from front of vehicle.