


General Information

Date & Time: 07, Jul, 2025 10:12

Make	Suzuki	Model	Carry
YOM	2024	Odo Meter Reading	9,885
Registration No.	NKE1452	Chassis No.	MHYDC61T4SJ210453
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	130.0	140	126	124
2	Boot Lid	139.0	120	138	159
3	Roof	112.7	118	120	105/108
4	Left Front Fender	131.6	131	134	130
5	Left Front Door	122.6	124	126	118
6	Center Panel Left	121.6	131	123	111
7	Left Rear Door	127.3	144	122	116
8	Left Back Panel	148.0	153	154	137
9	Right Front Fender	131.0	124	133	136
10	Right Front Door	113.3	113	115	112
11	Center Panel Right	119.3	112	126	120
12	Right Rear Door	114.6	120	109	115
13	Right Back Panel	161.6	156	165	164

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Worked - Small / Ceiling - Crinkle - Small	Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Center Panel - Scratch - Minimal / (R) Side Gate - Scratch - Medium / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Side Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Small / (L) Center Panel - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Roof - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, with warranty booklet, no jack, incomplete tools, with spare tire