

General Information

Date & Time: 09, Jul, 2025 08:40

Make	Chevrolet	Model	Spark
YOM	2014	Odo Meter Reading	81,170
Registration No.	ABA5298	Chassis No.	KLMF4811EC442953
CC	1.0	Transmission	M/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	130.0	124	130	136
2	Boot Lid	122.3	117	112	138
3	Roof	104.4	112	99	107/100
4	Left Front Fender	134.3	137	138	128
5	Left Front Door	141.6	120	140	165
6	Center Panel Left				
7	Left Rear Door	135.0	153	130	122
8	Left Back Panel	128.6	123	134	129
9	Right Front Fender	126.3	129	138	112
10	Right Front Door	148.6	159	138	149
11	Center Panel Right				
12	Right Rear Door	129.3	125	127	136
13	Right Back Panel	126.6	132	116	132

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Loose, Deformed - Medium / Sunvisor, Sunglass Holder - Loose, Deformed - Small / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Trunk Room - Loose, Deformed - Medium / Trim Other - Missing - Yes / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Dashboard - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Rear Windshield - Damaged - Small / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Door Lock - Issue - Yes / Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes with warranty booklet, no jack and tools, with spare tire, with LTO plate, reverse and plate light issue, scratches on headlight and tail light, suncrack headlights and tail light, yellowish headlight, back door handle issue, trunk floormat missing, rear wiper issue, room lamp issue, possible flooding, door lock issue, engine oil leaking, air-conditioning system issue, abnormal noise on rear door when opening, clutch and clutch pedal issue, non moving vehicle due to clutch issue</p>
