

General Information

Date & Time: 11, Nov, 2024 10:48

Make	Toyota	Model	Vios
YOM	2021	Mileage	154,851
Registration No.	DAU8636	Chassis No.	PA1B18F34M4140674
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	302.6	293	313	302
2	Boot Lid	310.0	329	325	276
3	Roof	212.2	227	215	207/200
4	Left Front Fender	215.6	212	215	220
5	Left Front Door	269.6	270	278	261
6	Center Panel Left				
7	Left Rear Door	326.6	320	356	304
8	Left Back Panel	220.0	233	216	211
9	Right Front Fender	367.3	246	591	265
10	Right Front Door	217.6	246	215	192
11	Center Panel Right				
12	Right Rear Door	677.6	722	610	701
13	Right Back Panel	690.6	358	456	1,258

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium	Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Dent - Small / (R) Step, In-panel, Side Spoiler - Dent - Small / (R) Rear Door, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Dent - Small / Roof - Dent - Small / (L) Rear Door, Molding - Scratch - Minimal
Frame Evaluation : B	Functional Evaluation : A
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Defects not found

Inspector Notes
no reverse camera/with spare tire & tools & warranty booklet