

General Information

Date & Time: 11, Nov, 2024 09:34

Make	Toyota	Model	Vios
YOM	2023	Mileage	15,013
Registration No.	CBI1137	Chassis No.	PA1B18F31P4208689
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	124.3	124	121	128
2	Boot Lid	125.0	125	125	125
3	Roof	123.2	124	115	133/121
4	Left Front Fender	109.3	113	109	106
5	Left Front Door	103.0	102	101	106
6	Center Panel Left				
7	Left Rear Door	117.6	123	117	113
8	Left Back Panel	117.3	123	118	111
9	Right Front Fender	112.3	110	110	117
10	Right Front Door	109.0	111	109	107
11	Center Panel Right				
12	Right Rear Door	115.3	106	113	127
13	Right Back Panel	114.6	105	116	123

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Horn - Issue - Yes

Inspector Notes

There's a warranty booklet and user manual. There's spare tire and tools.