


General Information

Date & Time: 16, Jul, 2025 13:19

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	12,409
Registration No.	DBQ7610	Chassis No.	PA1B18F33R4254303
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.9	106	98	105
2	Boot Lid	96.7	94	94	102
3	Roof	115.7	105	186	86/86
4	Left Front Fender	91.8	95	93	88
5	Left Front Door	93.7	99	88	94
6	Center Panel Left				
7	Left Rear Door	102.3	103	103	101
8	Left Back Panel	97.9	85	108	101
9	Right Front Fender	88.0	89	86	89
10	Right Front Door	96.0	100	97	92
11	Center Panel Right				
12	Right Rear Door	103.3	99	96	115
13	Right Back Panel	92.5	93	88	97

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Rear Trim - Cut, Crack - Minimal / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Carpet - Worked - Large / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Small / Overall Interior - Smell - Yes / (L) Front Seat - Worn - Yes / Ceiling - Grime - Minimal / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Minimal	Remarks Roof - Repair Traces - Yes / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Dent - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, with jack, no tools, with spare tire, with LTO plate, scratches on tail light, reverse light issue, trunk floormat missing