


General Information

Date & Time: 16, Jul, 2025 09:51

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	63,524
Registration No.	NGC4114	Chassis No.	PA1B18F3XP4200591
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	112	112	113
2	Boot Lid	98.4	93	100	102
3	Roof	85.7	91	86	81/85
4	Left Front Fender	97.4	97	96	100
5	Left Front Door	95.6	102	96	89
6	Center Panel Left				
7	Left Rear Door	101.4	102	99	103
8	Left Back Panel	131.0	111	139	143
9	Right Front Fender	98.7	97	103	97
10	Right Front Door	96.6	94	103	93
11	Center Panel Right				
12	Right Rear Door	102.4	87	92	129
13	Right Back Panel	98.4	93	96	106

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Medium / Ceiling - Grime - Small	Remarks Trunk Hood, Rear Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Dent - Medium / Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with spare tire/with jack and incomplete tools//No warranty booklet/No reverse camera
--