

General Information

Date & Time: 11, Jul, 2025 10:28

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	46,701
Registration No.	NHH1940	Chassis No.	PA1B18F3XP4231596
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.6	127	115	126
2	Boot Lid	117.0	118	110	123
3	Roof	103.2	106	101	108/98
4	Left Front Fender	177.0	184	186	161
5	Left Front Door	108.3	109	105	111
6	Center Panel Left				
7	Left Rear Door	111.6	112	105	118
8	Left Back Panel	113.0	119	108	112
9	Right Front Fender	108.6	114	101	111
10	Right Front Door	110.6	110	110	112
11	Center Panel Right				
12	Right Rear Door	109.0	115	103	109
13	Right Back Panel	118.6	114	112	130

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Medium / Overall Interior - Animal Hair - Yes	Remarks (L) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Small / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Crack, Gap - Medium
Frame Evaluation : C	Functional Evaluation : A
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, no warranty booklet, with jack, incomplete tools, with spare tire, cracked tail light, loosed cheek light, headlight scratch