

General Information

Date & Time: 12, Nov, 2024 07:56

Make	Toyota	Model	Vios
YOM	2024	Mileage	9,816
Registration No.	NFR3412	Chassis No.	PA1B18F33R4252115
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.6	125	124	122
2	Boot Lid	129.0	114	117	156
3	Roof	119.7	133	116	114/116
4	Left Front Fender	113.0	120	110	109
5	Left Front Door	111.6	112	108	115
6	Center Panel Left				
7	Left Rear Door	111.0	126	105	102
8	Left Back Panel	124.3	128	125	120
9	Right Front Fender	119.3	118	128	112
10	Right Front Door	113.0	111	110	118
11	Center Panel Right				
12	Right Rear Door	116.0	111	108	129
13	Right Back Panel	115.0	107	113	125

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Minimal	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Mirror - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
hairlines scratches around the vehicle/with spare tire/tools/warranty booklet