


General Information

Date & Time: 11, Nov, 2024 10:30

Make	Toyota	Model	Wigo
YOM	2024	Mileage	6,051
Registration No.	DBM5377	Chassis No.	MHKAA1BC7RJ015526
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	131.3	137	131	126
2	Boot Lid	98.3	102	98	95
3	Roof	94.1	90	94	105/88
4	Left Front Fender	113.0	114	115	110
5	Left Front Door	114.6	113	112	119
6	Center Panel Left				
7	Left Rear Door	109.6	113	110	106
8	Left Back Panel	110.0	111	106	113
9	Right Front Fender	101.5	101	100	104
10	Right Front Door	106.0	114	104	100
11	Center Panel Right				
12	Right Rear Door	107.3	103	103	116
13	Right Back Panel	99.1	99	97	101

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Minimal	Remarks (L) Rear Door, Molding - Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with warranty booklet and user manual. light scratches around the exterior. adhesive marks at the door panels.