

General Information

Date & Time: 21, Jul, 2025 10:24

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	19,499
Registration No.	DBM8898	Chassis No.	PA1B18F33R4246895
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	111	121	111
2	Boot Lid	105.2	108	99	109
3	Roof	103.9	105	110	95/106
4	Left Front Fender	101.3	106	102	96
5	Left Front Door	102.6	103	101	104
6	Center Panel Left				
7	Left Rear Door	102.6	106	102	100
8	Left Back Panel	105.3	104	110	102
9	Right Front Fender	101.0	107	97	100
10	Right Front Door	113.3	138	101	101
11	Center Panel Right				
12	Right Rear Door	109.6	105	117	107
13	Right Back Panel	110.6	109	110	113

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small	Remarks (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Member (Bolted) - Dent - Yes / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

With warranty booklet and LTO Plate, Jack and Sparetire, Incomplete Tools.