


General Information

Date & Time: 18, Jul, 2025 09:45

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	12,510
Registration No.	DBM3069	Chassis No.	MHKU3FE10PK005952
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	50.0	54	51	46
2	Boot Lid	94.4	114	64	105
3	Roof	59.8	49	44	83/64
4	Left Front Fender	47.0	48	47	46
5	Left Front Door	55.3	52	66	48
6	Center Panel Left	62.8	67	62	59
7	Left Rear Door	75.3	78	76	73
8	Left Back Panel	72.3	93	59	66
9	Right Front Fender	54.7	65	54	45
10	Right Front Door	51.1	48	49	57
11	Center Panel Right	57.1	60	52	60
12	Right Rear Door	52.0	47	46	63
13	Right Back Panel	51.4	53	54	48

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Large / Rear Gate - Scratch - Small / (L) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Dent - Medium / Roof - Dent - Medium / Cargo Bed Floor - Scratch - Large / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Front Panel - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate, no warranty booklet, no jack and tools, with spare tire