

General Information

Date & Time: 09, Nov, 2024 13:31

Make	Toyota	Model	Vios
YOM	2024	Mileage	23,436
Registration No.	DBN5332	Chassis No.	PA1B18F34P4231495
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.3	128	127	121
2	Boot Lid	128.0	109	139	136
3	Roof	108.7	116	110	102/107
4	Left Front Fender	114.6	115	114	115
5	Left Front Door	119.0	124	116	117
6	Center Panel Left				
7	Left Rear Door	114.3	116	113	114
8	Left Back Panel	124.3	135	130	108
9	Right Front Fender	126.0	120	115	143
10	Right Front Door	122.0	124	118	124
11	Center Panel Right				
12	Right Rear Door	121.0	119	118	126
13	Right Back Panel	119.3	112	109	137

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Lag - Grime - Small / (R) Front Seat - Grime - Large	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no reverse camera/hairlines scratches around the vehicle/front right seats dirty/rear seats dirty/ with spare tire/ jack and tools/ without warranty booklet