

General Information

Date & Time: 21, Jul, 2025 15:06

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	44,353
Registration No.	NHI8635	Chassis No.	PA1B18F32P4207941
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.0	105	102	108
2	Boot Lid	107.6	104	108	111
3	Roof	96.0	105	96	94/90
4	Left Front Fender	98.2	100	96	99
5	Left Front Door	97.1	98	96	97
6	Center Panel Left				
7	Left Rear Door	104.9	114	107	94
8	Left Back Panel	109.5	117	99	113
9	Right Front Fender	94.6	93	95	95
10	Right Front Door	93.9	94	90	98
11	Center Panel Right				
12	Right Rear Door	99.2	93	97	108
13	Right Back Panel	99.8	96	101	102

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Seat - Grime - Medium / (L) Front Trim - Grime - Medium / Ceiling - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/No spare tire/With jack and tools/No warranty booklet/No reverse camera