


General Information

Date & Time: 21, Jul, 2025 12:58

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	111,013
Registration No.	NHC4257	Chassis No.	PA1B18F34N4195708
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.0	103	116	105
2	Boot Lid	100.8	99	100	104
3	Roof	92.9	117	80	86/89
4	Left Front Fender	93.4	100	89	91
5	Left Front Door	95.2	96	93	97
6	Center Panel Left				
7	Left Rear Door	97.2	103	99	90
8	Left Back Panel	98.4	100	96	99
9	Right Front Fender	100.6	89	120	93
10	Right Front Door	93.6	99	92	91
11	Center Panel Right				
12	Right Rear Door	93.3	91	92	96
13	Right Back Panel	93.2	91	89	99

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes / (L) Front Floor Mat - Worked - Large / Ceiling - Crinkle - Medium / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small	Remarks Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Dent - Minimal / (L) Front Tyre - Crack, Cut - Yes / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
With warranty booklet and LTO Plate, Jack and Sparetire, Incomplete Tools. scratch headlight and tail light and plate light busted, worn tires.