

General Information

Date & Time: 11, Nov, 2024 09:01

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,994
Registration No.	DBO5754	Chassis No.	PA1B18F3XP4238659
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	162.3	160	163	164
2	Boot Lid	151.3	149	141	164
3	Roof	154.0	167	158	157/134
4	Left Front Fender	148.6	146	143	157
5	Left Front Door	158.0	159	153	162
6	Center Panel Left				
7	Left Rear Door	156.0	165	157	146
8	Left Back Panel	151.0	162	151	140
9	Right Front Fender	161.6	169	153	163
10	Right Front Door	121.6	123	119	123
11	Center Panel Right				
12	Right Rear Door	129.6	129	126	134
13	Right Back Panel	140.3	143	134	144

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (R) Mirror - Faded(Color, Gloss) - Yes / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

hairlines scratches/with spare tire & tool & warranty booklet