


General Information

Date & Time: 18, Jul, 2025 15:41

Make	Toyota	Model	Wigo
YOM	2021	Odo Meter Reading	55,975
Registration No.	DAV7542	Chassis No.	MHKA4DF5FMJ055068
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	83.5	80	87	83
2	Boot Lid	84.7	87	88	79
3	Roof	79.2	71	83	87/76
4	Left Front Fender	126.6	121	163	96
5	Left Front Door	87.0	90	87	85
6	Center Panel Left				
7	Left Rear Door	90.8	90	92	91
8	Left Back Panel	85.4	87	87	83
9	Right Front Fender	191.0	110	132	331
10	Right Front Door	86.5	86	85	89
11	Center Panel Right				
12	Right Rear Door	87.6	94	87	82
13	Right Back Panel	93.3	94	96	90

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Small / (L) Front Trim - Grime - Medium	Remarks (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Large / (L) Front Fender, Molding - Crack, Gap - Medium / Bonnet, Headlight - Crack, Gap - Large / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Small / Roof - Scratch - Medium / (L) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/No jack and tools/No warranty booklet/ rear side tail light crack issue/front right fog light issue/rear seat issue/trunk barrier missing