


General Information

Date & Time: 21, Jul, 2025 10:23

Make	Toyota	Model	Innova
YOM	2021	Odo Meter Reading	29,383
Registration No.	NFC2663	Chassis No.	PA2JA8EM6M0093415
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.3	91	115	104
2	Boot Lid	96.0	92	99	97
3	Roof	94.8	87	82	120/90
4	Left Front Fender	98.7	100	99	98
5	Left Front Door	115.6	119	116	112
6	Center Panel Left				
7	Left Rear Door	159.3	145	164	169
8	Left Back Panel	102.7	107	102	99
9	Right Front Fender	96.5	92	98	100
10	Right Front Door	98.9	90	105	102
11	Center Panel Right				
12	Right Rear Door	105.6	109	109	99
13	Right Back Panel	106.6	103	100	117

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small / Ceiling - Grime - Small / Overall Interior - Animal Hair - Yes / Dashboard - Traces of Adhesive Tape - Yes	Remarks (L) Rear Door - Repair Traces - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Mirror - Crack - Damaged
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
With warranty booklet, Jack and Sparetire, Incomplete Tools. improvise LTO plate,no original LTO PLATE, right side mirror housing Crack,