

General Information

Date & Time: 18, Jul, 2025 09:35

Make	Toyota	Model	Fortuner
YOM	2021	Odo Meter Reading	70,761
Registration No.	NEL1246	Chassis No.	MHFCB8GS7L0519780
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.3	114	109	102
2	Boot Lid	407.0	165	681	375
3	Roof	125.7	117	127	114/145
4	Left Front Fender	103.0	89	118	102
5	Left Front Door	103.1	106	99	104
6	Center Panel Left				
7	Left Rear Door	90.8	101	89	83
8	Left Back Panel	105.3	108	105	103
9	Right Front Fender	98.6	107	97	92
10	Right Front Door	114.3	137	99	107
11	Center Panel Right				
12	Right Rear Door	95.6	92	94	101
13	Right Back Panel	108.7	102	98	126

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small / (L) Rear Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Member (Bolted) - Dent - Yes / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With LTO plate and warranty booklet and Sparetire, Incomplete Tools, Jack. scratch headlight and tail light. adhesive marks on rear fender and rear door.