

General Information

Date & Time: 11, Nov, 2024 12:45

Make	Toyota	Model	Vios
YOM	2024	Mileage	1,234
Registration No.	NHR 5401	Chassis No.	PA1B18F30P4229758
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.3	119	108	122
2	Boot Lid	119.0	111	121	125
3	Roof	109.7	114	108	105/112
4	Left Front Fender	107.6	110	109	104
5	Left Front Door	105.3	114	100	102
6	Center Panel Left				
7	Left Rear Door	104.3	105	102	106
8	Left Back Panel	120.3	126	123	112
9	Right Front Fender	109.6	108	109	112
10	Right Front Door	107.0	108	108	105
11	Center Panel Right				
12	Right Rear Door	108.0	109	108	107
13	Right Back Panel	122.0	116	119	131

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Overall Interior - Smell - Yes / Rear Seat - Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Crack, Gap - Small / (L) Front Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
swirlmarks and hairline scratches around the exterior.No user manual, warranty booklet and tools.