

General Information

Date & Time: 18, Jul, 2025 09:01

Make	Mitsubishi	Model	Mirage
YOM	2023	Odo Meter Reading	23,272
Registration No.	EAG1556	Chassis No.	PAEA13TJPPA005183
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.0	120	119	112
2	Boot Lid	105.0	105	108	102
3	Roof	99.6	101	95	100/103
4	Left Front Fender	108.0	108	109	107
5	Left Front Door	105.3	110	102	104
6	Center Panel Left				
7	Left Rear Door	103.1	107	97	105
8	Left Back Panel	106.3	108	107	104
9	Right Front Fender	108.3	103	105	117
10	Right Front Door	108.3	111	107	107
11	Center Panel Right				
12	Right Rear Door	105.3	108	100	108
13	Right Back Panel	109.0	101	105	121

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Dashboard - Traces of Adhesive Tape - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Rear Seat - Grime - Large / Ceiling - Grime - Medium</p>	<p>Remarks (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>1 key. with Lto plate, with jack, no warranty booklet, no tools, left rear fender has paint mark, rear seat issue</p>