

General Information

Date & Time: 13, Nov, 2024 11:04

Make	Toyota	Model	Innova
YOM	2024	Mileage	21,228
Registration No.	DBO4673	Chassis No.	PA2JA8EM9P0133331
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	135.3	138	140	128
2	Boot Lid	120.3	119	117	125
3	Roof	119.5	123	120	115/120
4	Left Front Fender	117.0	116	122	113
5	Left Front Door	119.3	123	120	115
6	Center Panel Left				
7	Left Rear Door	126.3	129	133	117
8	Left Back Panel	126.3	125	123	131
9	Right Front Fender	120.6	122	124	116
10	Right Front Door	127.3	123	134	125
11	Center Panel Right				
12	Right Rear Door	124.0	117	126	129
13	Right Back Panel	129.6	132	128	129

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Door, Molding - Scratch & Dent - Minimal / (L) Mirror - Crack - Damaged / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

missing right side mirror cover/ with tools and spare tire/ no warranty booklet