

General Information

Date & Time: 18, Jul, 2025 10:32

Make	Ford	Model	Everest
YOM	2016	Odo Meter Reading	153,018
Registration No.	CAC1419	Chassis No.	MNCAXXMAWAGC19589
CC	3.2	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Gray		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.0	91	98	102
2	Boot Lid	106.6	101	121	98
3	Roof	112.5	119	104	116/111
4	Left Front Fender	103.3	107	102	101
5	Left Front Door	111.3	113	108	113
6	Center Panel Left				
7	Left Rear Door	139.0	139	134	144
8	Left Back Panel	158.0	181	147	146
9	Right Front Fender	155.3	147	154	165
10	Right Front Door	154.0	164	149	149
11	Center Panel Right				
12	Right Rear Door	173.6	171	170	180
13	Right Back Panel	107.3	112	105	105

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	E	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Ceiling - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Worn - Yes / (R) Front Seat - Cigarette Burns - Burnt Minimal / (R) Rear Trim - Grime - Medium / Rear Seat - Worn - Yes / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Cut, Crack - Large / Steering Wheel - Worn, Peel, Crack - Large / (R) Front Trim - Cut, Crack - Medium / Console, Switches, Vents - Traces of Adhesive Tape - Yes</p>		<p>Remarks (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / Roof - Scratch - Small / (R) Mirror - Crack - Cracks / (L) Mirror - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Repair mark - Yes / Member (Bolted) - Dent - Yes</p>	
Frame Evaluation :	B	Functional Evaluation :	C
<p>Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p>Remarks Warning Lamps - Issue - Yes / Reverse Camera - N/A - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>Possible flooding. Check engine. TPS monitor warning. Audio Display view issue. both sunvisor issue. worn seats. Gap at front bumper and front right fender. Front toe hook cover missing. Center glovebox issue. Without warranty booklet, tools and jack. With spare tire. 1 key. With LTO plate.</p>