

General Information

Date & Time: 23, Jul, 2025 13:18

Make	Toyota	Model	Fortuner
YOM	2023	Odo Meter Reading	34,085
Registration No.	CBT7270	Chassis No.	MHFCB8GS6P3527017
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.6	113	130	113
2	Boot Lid	101.7	85	104	116
3	Roof	113.2	115	107	121/110
4	Left Front Fender	106.0	100	105	113
5	Left Front Door	105.3	102	103	111
6	Center Panel Left				
7	Left Rear Door	96.1	106	92	90
8	Left Back Panel	114.3	122	112	109
9	Right Front Fender	112.0	125	111	100
10	Right Front Door	155.3	171	153	142
11	Center Panel Right				
12	Right Rear Door	104.0	101	104	107
13	Right Back Panel	115.0	112	109	124

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain Remarks Overall Interior - Smell - Yes / Ceiling - Grime - Small / Rear Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap Remarks (L) Front Fender, Molding - Scratch & Dent - Medium / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Roof - Scratch - Small / Bonnet, Headlight - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With LTO plate, Jack and Sparetire, Incomplete Tools. no warranty booklet and scratch headlight and tail light. worn tires.