

## General Information

Date & Time: 21, Jul, 2025 08:13

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	16,732
<b>Registration No.</b>	NKJ4758	<b>Chassis No.</b>	PA1B18F34R4266962
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.6	108	121	124
2	Boot Lid	126.0	128	121	129
3	Roof	117.0	104	112	149/103
4	Left Front Fender	110.0	105	113	112
5	Left Front Door	141.0	130	158	135
6	Center Panel Left				
7	Left Rear Door	154.3	159	148	156
8	Left Back Panel	138.0	154	126	134
9	Right Front Fender	108.3	107	104	114
10	Right Front Door	94.2	90	96	97
11	Center Panel Right				
12	Right Rear Door	98.1	97	100	97
13	Right Back Panel	112.6	111	111	116

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Small / (R) Front Trim - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Medium / Mat Other - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Medium</p>	<p><b>Remarks</b> (L) Mirror - Scratch - Minimal / Member (Bolted) - Dent - Yes / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Crack taillight. Without jack. With warranty booklet, spare tire, tools, and seat cover. 1 key. With LTO plate.</p>